

**New Jersey Department of Transportation
Bureau of Materials Engineering and Testing**

Cold Patch Data Collection Form

Product : Q.P.R. - 2000

Location : Rt. 21 SB MP 12.0 Passaic

Inspection Date : 4/17/97 (6 months)

Pothole No.

	1	2	3	4	5	Avg.
Bleeding	10	10	10	10	10	10.0
Cracking	10	10	10	10	10	10.0
Dishing	10	10	10	10	10	10.0
Edge Disintegration	10	10	10	10	10	10.0
Missing Patch	10	7	10	10	10	9.4
Raveling	10	10	10	10	10	10.0
Shoving	10	10	10	10	10	10.0
Overall average =						9.9

Rating : 0 = Worst
10 = Best

Comments : Poor workability - moderate clumping of material in container was hard to break up - stuck to tools.